

Client:

Paseo Grande

Property:

11611 Paseo Grande BLVD

Fort Myers, FL 33912

Operator:

**ZLYON** 

Estimator:

Zachary Lyons

Position:

Project Manager

Company:

Fireservice Inc.

Business:

3120 Winkler Ave. Ext.

Fort Myers, FL 33916

Type of Estimate:

Water Damage

Date Entered:

8/2/2024

Date Assigned:

(239) 823-7128

zlyons@fireserviceusa.com

Business:

E-mail:

Price List:

FLFM8X JUL24

Labor Efficiency:

Restoration/Service/Remodel

Estimate:

82182-34890-R

File Number:

Mold

#### REMEDIATION

#### Please note:

- 1. All work to be completed to the standards of the IICRC S520 Mold Remediation Manual, the NADCA ACR standards, and Florida State Guidelines for remediation.
- 2. We can not guarantee that this issue will not reoccur if the underlying moisture issues occurring in the structure are not resolved.
- 3. Processing of any clothing/linens/draperies to be completed by others.
- 4. Contents not included or deemed non-salvageable will be bagged and/or wrapped in plastic and left in the rooms they were located as space allows.
- 5. If additional damage is found during the remediation process, a supplemental estimate will be provided for approval.
- 6. This estimate will be honored for 30 days from the date of submission. After 30 days this estimate is subject to market adjustment due to the rising costs of construction materials and increased labor costs.



# 82182-34890-R Main Level

Reception Area				Height: 16'
Missing Wall - Goes to Floor	4' 10" X 6' 8"	Opens into	Exterior	
Missing Wall - Goes to Floor	3' 4" X 6' 8"	Opens into	Exterior	
DESCRIPTION		QTY	UNIT PRICE	TOTAL
1. Scaffold - per section (per week)		4.00 WK @	60.43 =	241.72
4 sections of scaffolding				
2. Labor to set up and take down scaffold - per section		4.00 EA @	38.38 =	153.52
3. Containment Barrier/Airlock/Decon. Chamber		48.00 SF @	1.26 =	60.48
4. Peel & seal zipper		1.00 EA @	15.42 =	15.42
5. HEPA Vacuuming - Light - (PER SF)		1,789.71 SF @	0.53 =	948.55
6. Deodorize building - Ozone & hydroxyl treatment		5,530.65 CF @	0.05 =	276.53
7. Apply plant-based anti-microbial agent to more than the walls and ceiling		1,789.71 SF @	0.39 =	697.99
8. Neg. air fan/Air scrubLarge (per 24 hr period)-No monit.		4.00 DA @	105.50 =	422.00
9. Dehumidifier (per 24 hr period)- 110-159 ppd - No monitor.		4.00 DA @	112.48 =	449.92

Dining Area			Height: 16'
DESCRIPTION	QTY	UNIT PRICE	TOTAL
10. Scaffold - per section (per week)	4.00 WK @	60.43 =	241.72
4 sections of scaffolding			
11. Labor to set up and take down scaffold - per section	4.00 EA @	38.38 =	153.52
12. HEPA Vacuuming - Light - (PER SF)	2,515.70 SF @	0.53 =	1,333.32
13. Deodorize building - Ozone & hydroxyl treatment	8,503.72 CF @	0.05 =	425.19
14. Apply plant-based anti-microbial agent to more than the walls and ceiling	2,515.70 SF @	0.39 =	981.12
15. Containment Barrier/Airlock/Decon. Chamber	462.00 SF @	1.26 =	582.12
16. Peel & seal zipper	2.00 EA @	15.42 =	30.84
17. Neg. air fan/Air scrubLarge (per 24 hr period)-No monit.	4.00 DA @	105.50 =	422.00
18. Dehumidifier (per 24 hr period)- 110-159 ppd - No monitor.	4.00 DA @	112.48 =	449.92

Ice Cream Parlor				Height: 12'
Missing Wall - Goes to Floor	3' 8" X 6' 8"	Opens into		
Missing Wall - Goes to Floor	3' 4" X 6' 8"	Opens into	Exterior	
DESCRIPTION		QTY	UNIT PRICE	TOTAL
82182-34890-R			8/2/2024	Page: 2



## **CONTINUED - Ice Cream Parlor**

DESCRIPTION	QTY	UNIT PRICE	TOTAL
19. HEPA Vacuuming - Light - (PER SF)	968.32 SF @	0.53 =	513.21
20. Deodorize building - Ozone & hydroxyl treatment	2,238.02 CF @	0.05 =	111.90
21. Apply plant-based anti-microbial agent to more than the walls and ceiling	968.32 SF @	0.39 =	377.64
22. Containment Barrier/Airlock/Decon. Chamber	48.00 SF @	1.26 =	60.48
23. Neg. air fan/Air scrubLarge (per 24 hr period)-No monit.	4.00 DA @	105.50 =	422.00
24. Dehumidifier (per 24 hr period)- 110-159 ppd - No monitor.	4.00 DA @	112.48 =	449.92

Paseo Entry				Height: 12'
Missing Wall - Goes to Floor	4' 3" X 6' 8"	Opens into Opens into		
Missing Wall - Goes to Floor	4' X 6' 8"	Opens into	Exterior	
DESCRIPTION		QTY	UNIT PRICE	TOTAL
25. Scaffold - per section (per week)		4.00 WK @	60.43 =	241.72
4 sections of scaffolding				
26. Labor to set up and take down scaffold - per section		4.00 EA @	38.38 =	153.52
27. Containment Barrier/Airlock/Decon. Chamber		90.00 SF @	1.26 =	113.40
28. Peel & seal zipper		1.00 EA @	15.42 =	15.42
29. HEPA Vacuuming - Light - (PER SF)		1,166.16 SF @	0.53 =	618.06
30. Deodorize building - Ozone & hydroxyl treatment		2,662.86 CF @	0.05 =	133.14
31. Apply plant-based anti-microbial agent to more than the walls and		1,166.16 SF @	0.39 =	454.80
ceiling				
32. Neg. air fan/Air scrubLarge (per 24 h	r period)-No monit.	4.00 DA @	105.50 =	422.00
33. Dehumidifier (per 24 hr period)- 110-159 ppd - No monitor.		4.00 DA @	112.48 =	449.92

### Miscellaneous

DESCRIPTION	QTY	UNIT PRICE	TOTAL
34. Water Extraction & Remediation Technician - per hour	60.00 HR @	71.92 =	4,315.20
Moving/cleaning of contents and horizontal surfaces in affected area- ele	ectronics, drywall, light f	ixtures, etc.	
<ul><li>35. Equipment setup, take down, and monitoring (hourly charge)</li><li>.33 HOURS PER PIECE OF EQUIPMENT</li></ul>	2.64 HR @	71.92 =	189.87
22182-34890-R		8/2/2024	Page: 3



## **CONTINUED - Miscellaneous**

DESCRIPTION	QTY	UNIT PRICE	TOTAL
36. Equipment decontamination charge - per piece of equipment	8.00 EA @	42.67 =	341.36
1 per piece of equipment charged 37. Add for personal protective equipment (hazardous cleanup)	16.00 EA @	12.28 =	196.48
1 per technician per day 38. Add for HEPA filter (for neg. air machine/vacuum - Large)	4.00 EA @	326.26 =	1,305.04
39. Post Remediation Testing - air or surface testing, lab analysis, with	1.00 EA @	916.67 =	916.67
final report 40. Cleaning of HVAC ductwork, plenums, and coils - Commercial	1.00 HR @	2,500.00 =	2,500.00
Negative pressure cleaning of hvac system.			

# **Grand Total Areas:**

1,285.55	SF Walls SF Floor SF Long Wall	142.84	SF Ceiling SY Flooring SF Short Wall	257.71	SF Walls and Ceiling LF Floor Perimeter LF Ceil. Perimeter
	Floor Area Exterior Wall Area	<i>'</i>	Total Area Exterior Perimeter of Walls	3,868.78	Interior Wall Area
	Surface Area Total Ridge Length		Number of Squares Total Hip Length	0.00	Total Perimeter Length

Page: 4 8/2/2024 82182-34890-R




# **Summary**


Net Claim	<u>\$22,382.00</u>
Replacement Cost Value	\$22,382.00
Total Cleaning Tax	61.53
Subtotal	22,320.47
Material Sales Tax	132.84
Line Item Total	22,187.63

Zachary Lyons Project Manager


Page: 5 8/2/2024 82182-34890-R

#### Main Level











Main Level

8/2/2024

Page: 6

82182-34890-R